


# METAL EARTH™



## 3D LASER CUT MODELS



It is highly recommended that you visit  
[www.fascinations.com/metalearth360/mms050](http://www.fascinations.com/metalearth360/mms050)  
 to see the completed model before assembling your own



mms050





Metal sheet

To create the best connections

● Insert tab and bend 90 degrees for most visible areas

▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

### Assembly Flow Chart

